

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	L1	330	Mast.in.	USPAT	2005/01/04 09:10	
2	BRS	L2	7	1 and pressure adj sensor	USPAT	2005/01/04 09:09	
3	BRS	L3	17	1 and collar	USPAT	2005/01/04 09:09	
4	BRS	L4	17	1 and collar	US- PGPUB ; USPAT	2005/01/04 09:09	
5	BRS	L5	69	Mast.in.	US- PGPUB	2005/01/04 09:10	
6	BRS	L6	1	5 and collar	US- PGPUB	2005/01/04 10:35	
7	BRS	L7	18964	boundary adj layer	US- PGPUB ; USPAT ; DERWE NT	2005/01/04 10:36	
8	BRS	L8	146	7 and pressure and probe and (aircraft airplane)	US- PGPUB ; USPAT ; DERWE NT	2005/01/04 10:37	
9	BRS	L9	7	8 and corrugation\$3	US- PGPUB ; USPAT ; DERWE NT	2005/01/04 10:51	
10	BRS	L10	0	8 and upstrweam adj corrugation\$3	US- PGPUB ; USPAT ; DERWE NT	2005/01/04 10:51	

	Error Definition	Err ors
1		
2		
3		
4		
5		
6		
7		
8		
9		
10		

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
11	BRS	L11	0	8 and upstream adj corrugation\$3	US- PGPUB ; USPAT ; DERWE NT	2005/01/0 4 10:51	
12	BRS	L12	0	7 and upstream adj corrugation\$3	US- PGPUB ; USPAT ; DERWE NT	2005/01/0 4 10:51	

	Error Definition	Err ors
11		
12		